


How to make label

First make sure the CorelDRAW plug-in and sheet cutting machine driver has been installed successfully.


Step1: Turn CorelDRAW on, Setting document size.






ANHUI WILLIAM CNC TECHNOLOGY CO.,LTD

Step2: Add marks



Step3: Import label (to make sure that the label file includes label and contour lines)




www.vicutcnc.com



ANHUI WILLIAM CNC TECHNOLOGY CO.,LTD



Step4: Move “contour line” to “OutLine Layer”(“label” in “layer1”, “contour line” in “OutLine Layer”)






ANHUI WILLIAM CNC TECHNOLOGY CO.,LTD


Step5-1: Save print file,Click P, and then save the print file, easy to print)



Step5-2: Click P ,Connect to printer, print directly.










ANHUI WILLIAM CNC TECHNOLOGY CO.,LTD





ANHUI WILLIAM CNC TECHNOLOGY CO.,LTD

Step 6-2: Use USB cut directly. Click “O” than to click “C”

(save –sheet cutter –top left corner–print)

